







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(\text{n,el.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(\text{n,tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abcissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).




Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$




Correlation Matrix





Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{el.})$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{56}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{el.})$





Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{el.})$




Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.




Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.



Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{nonel.})$



Correlation Matrix






Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{nonel.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{nonel.})$





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{inel.})$



Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{inel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n_1)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\gamma)$





Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,p)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\alpha)$





Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix








Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,np)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{56}\text{Fe}(n,np)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{nd})$



Ordinate scales are % relative standard deviation and barns.




Abscissa scales are energy (eV).

σ vs. E for $^{56}\text{Fe}(n,\text{nd})$




Correlation Matrix






Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n_{\text{cont}})$.



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n, n_1)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n_1)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.




Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.






Correlation Matrix








Correlation Matrix







Correlation Matrix







Correlation Matrix






Warning: some uncertainty data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix






Warning: some uncertainty data were suppressed.



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Warning: some uncertainty
data were suppressed.






Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,t)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Warning: some uncertainty data were suppressed.

σ vs. E for $^{56}\text{Fe}(n,t)$



Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Warning: some uncertainty data were suppressed.



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,p\alpha)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{56}\text{Fe}(n,p\alpha)$




10^7



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{pd})$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{56}\text{Fe}(n,\text{pd})$




10^7



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(\text{mt117})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{56}\text{Fe}(\text{mt117})$



Correlation Matrix

