








Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$




Ordinate scale is %
relative standard deviation.



Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$




Correlation Matrix





Correlation Matrix




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,p)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{tot.})$





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(\text{n,inel.})$




Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(\text{n,el.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{el.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,p)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{el.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(\text{n,inel.})$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(\text{n,nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{nonel.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{nonel.})$



Correlation Matrix








Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,p)$




Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{inel.})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{56}\text{Fe}(n,\text{inel.})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{inel.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(\text{n},\text{ncont.})$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(\text{n},\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{inel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,p)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{inel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n_1)$




Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$




Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\gamma)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,p)$




Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\alpha)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\alpha)$





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{56}\text{Fe}(n,n\alpha)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,np)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{56}\text{Fe}(n,np)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{nd})$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{56}\text{Fe}(n,\text{nd})$





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n_{\text{cont}})$.



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n_1)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.


$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n_1)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,p)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n_1)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abcissa scales are energy (eV).





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n_4)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{56}\text{Fe}(n,n_4)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{56}\text{Fe}(n,n\text{cont.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,p)$





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\gamma)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,d)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{56}\text{Fe}(n,d)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,t)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{56}\text{Fe}(n,t)$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{He3})$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

σ vs. E for $^{56}\text{Fe}(n,\text{He3})$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,p\alpha)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{56}\text{Fe}(n,p\alpha)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(n,\text{pd})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{56}\text{Fe}(n,\text{pd})$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{56}\text{Fe}(\text{mt117})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{56}\text{Fe}(\text{mt117})$



Correlation Matrix

