








Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix








Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\text{tot.})$





Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,2n)$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\text{tot.})$





Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(\text{n},\text{ncont.})$




Ordinate scale is %  
relative standard deviation.




Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(\text{n},\text{tot.})$




Correlation Matrix







Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abcissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,2n)$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\text{el.})$





Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(\text{n},\text{ncont.})$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(\text{n},\text{el.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,2n)$



Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\text{nonel.})$





Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abcissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(\text{n},\text{ncont.})$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(\text{n},\text{nonel.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\text{nonel.})$





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,2n)$




Ordinate scale is %  
relative standard deviation.





Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\text{inel.})$




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(\text{n},\text{ncont.})$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(\text{n},\text{inel.})$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\gamma)$





Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\text{inel.})$





Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abcissa scales are energy (eV).



Correlation Matrix








Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,2n)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{46}\text{Ti}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,n_1)$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,2n)$



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,n\text{cont.})$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\gamma)$




Ordinate scale is %  
relative standard deviation.

Abcissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,p)$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,2n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\alpha)$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,2n)$



Correlation Matrix








Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,np)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{46}\text{Ti}(n,np)$





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,n_{\text{cont}})$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n, n_1)$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,n_3)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{46}\text{Ti}(n,n_3)$





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.





Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).



Warning: some uncertainty  
data were suppressed.




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,t)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{46}\text{Ti}(n,t)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\text{He3})$



Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{46}\text{Ti}(n,\text{He3})$



Correlation Matrix








Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,p\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{46}\text{Ti}(n,p\alpha)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{46}\text{Ti}(n,\text{pd})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{46}\text{Ti}(n,\text{pd})$



Correlation Matrix

