




$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{tot.})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{61}\text{Co}(n,\text{tot.})$




Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{el.})$




$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{tot.})$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{nonel.})$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{tot.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,2n)$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{tot.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abcissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\gamma)$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{tot.})$



Correlation Matrix









Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).




Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{tot.})$




Correlation Matrix






Correlation Matrix




$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{el.})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{61}\text{Co}(n,\text{el.})$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{nonel.})$





Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{inel.})$




Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,2n)$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{el.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{el.})$




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\gamma)$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{el.})$



Correlation Matrix








Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.



Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$  vs.  $E$  for  $^{61}\text{Co}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,2n)$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{nonel.})$



Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{nonel.})$





Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).




Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\gamma)$





Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{nonel.})$



Correlation Matrix








Ordinate scale is %  
relative standard deviation.




Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.




Correlation Matrix






Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{inel.})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{61}\text{Co}(n,\text{inel.})$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,2n)$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{inel.})$




Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix








Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix







Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,2n)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{61}\text{Co}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,3n)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{61}\text{Co}(n,3n)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,n\alpha)$





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{61}\text{Co}(n,n\alpha)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,2n\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{61}\text{Co}(n,2n\alpha)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,np)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


$\sigma$  vs. E for  $^{61}\text{Co}(n,np)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{nd})$





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{61}\text{Co}(n,\text{nd})$




Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,nt)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{61}\text{Co}(n,nt)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,2np)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

$\sigma$  vs. E for  $^{61}\text{Co}(n,2np)$





Correlation Matrix










Ordinate scales are % relative standard deviation and barns.

Abcissa scales are energy (eV).




Correlation Matrix







$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\gamma)$




Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,n_1)$



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.



Correlation Matrix








Ordinate scale is %  
relative standard deviation.


Abcissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix













Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).




Correlation Matrix







Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %  
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty  
data were suppressed.





Correlation Matrix







Warning: some uncertainty data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\gamma)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{61}\text{Co}(n,\gamma)$



Correlation Matrix








Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix









Ordinate scale is %  
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty  
data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,d)$





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{61}\text{Co}(n,d)$



Correlation Matrix



$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,t)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


$\sigma$  vs. E for  $^{61}\text{Co}(n,t)$



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,\text{He3})$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{61}\text{Co}(n,\text{He3})$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix





$\Delta\sigma/\sigma$  vs. E for  $^{61}\text{Co}(n,p\alpha)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

$\sigma$  vs. E for  $^{61}\text{Co}(n,p\alpha)$



Correlation Matrix

