







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{nonel.})$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{inel.})$




Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{tot.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,2n)$




Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{tot.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix








Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix









Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).




Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{nonel.})$




$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{el.})$




Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{el.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{el.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{ncont.})$



Ordinate scale is %
relative standard deviation.




Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{el.})$




Correlation Matrix







Correlation Matrix











Warning: some uncertainty
data were suppressed.



Correlation Matrix










Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{nonel.})$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{nonel.})$



Correlation Matrix







Ordinate scale is %
relative standard deviation.




Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n, n_{\text{nonel}})$




Correlation Matrix







Correlation Matrix







Warning: some uncertainty
data were suppressed.



Correlation Matrix







Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.





Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,2n)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{inel.})$



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{inel.})$





Correlation Matrix






Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,p)$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{inel.})$




Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,2n)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{64}\text{Cu}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,n_1)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,n\text{cont.})$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,2n)$





Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abcissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,p)$



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,2n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\alpha)$




Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,2n)$



Correlation Matrix




$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,3n)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{64}\text{Cu}(n,3n)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,n\alpha)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{64}\text{Cu}(n,n\alpha)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,2n\alpha)$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{64}\text{Cu}(n,2n\alpha)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,np)$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


σ vs. E for $^{64}\text{Cu}(n,np)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{nd})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{64}\text{Cu}(n,\text{nd})$



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,nt)$





Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{64}\text{Cu}(n,nt)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,2np)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

σ vs. E for $^{64}\text{Cu}(n,2np)$




Correlation Matrix





Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,n_{\text{cont}})$



Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,n_1)$



Correlation Matrix






Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,n_1)$



Correlation Matrix







Ordinate scale is %
relative standard deviation.




Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,n_1)$





Correlation Matrix








Correlation Matrix






Correlation Matrix







Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix






Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).





Correlation Matrix





Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,p)$




Ordinate scale is %
relative standard deviation.


Abscissa scales are energy (eV).

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,n\text{cont.})$





Correlation Matrix









Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).





Correlation Matrix





Correlation Matrix






Correlation Matrix



Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).

Warning: some uncertainty
data were suppressed.




Ordinate scale is %
relative standard deviation.

Abscissa scales are energy (eV).


Warning: some uncertainty
data were suppressed.

$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\gamma)$



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.



Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.




Correlation Matrix







Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).



Correlation Matrix







Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,\text{He3})$




Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.

σ vs. E for $^{64}\text{Cu}(n,\text{He3})$



Correlation Matrix








Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).


Warning: some uncertainty data were suppressed.



Correlation Matrix



$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(n,p\alpha)$




Ordinate scales are % relative standard deviation and barns.


Abscissa scales are energy (eV).

Warning: some uncertainty data were suppressed.


σ vs. E for $^{64}\text{Cu}(n,p\alpha)$



Correlation Matrix





$\Delta\sigma/\sigma$ vs. E for $^{64}\text{Cu}(\text{mt117})$



Ordinate scales are % relative standard deviation and barns.

Abscissa scales are energy (eV).

σ vs. E for $^{64}\text{Cu}(\text{mt117})$



Correlation Matrix

